

NAWS China Lake Earthquake Response and Recovery



Presented by:

David B. Swanson, P.E., S.E.
Principal, LEED AP, F. SEI

SAME San Diego Post Luncheon
September 11, 2019

ReidMiddleton




Naval Air Weapons Station China Lake

Overview

Naval Air Weapons Station China Lake

- Western Mojave Desert region of California
- 150 miles north of Los Angeles
- Navy's largest single land holding
- Over 1.1 million acres—larger than the state of Rhode Island
- 85% of the Navy's land for weapons and armaments research, development, acquisition, testing and evaluation
- 38% of the Navy's land holding worldwide



Sources:

https://www.cnrc.navy.mil/regions/cnrsw/installations/naws_china_lake.html

<https://defensetudies.net/pages/naval-air-weapons-station-china-lake-small-business-contracting>

<https://i.pinimg.com/originals/a0/0b/ef/a00befb394804b74433801e8e2d33908.jpg>

Location - NAWS China Lake




Source:
<https://www.google.com/maps/place/Naval+Air+Weapons+Station+China+Lake/@35.6921236,-118.4388467,10z/data=!4m5!3m4!1s0x80c1124b2c5e64d5:0xba9250134ea239e8!8m2!3d35.6551706!4d-117.6574374>



July 4th and 5th, 2019 Searles Valley Earthquakes

First Earthquake M6.4 ShakeMap

- M6.4 Earthquake
- 10:33A Local Time
- July 4th Holiday
- Epicenter 7.5 miles SW of Searles Valley
- 6.4 miles Deep




PERCEIVED SHAKING	Not felt	Weak	Light	Moderate	Strong	Very strong	Severe	Violent	Extreme
POTENTIAL DAMAGE	none	none	none	Very light	Light	Moderate	Mod./Heavy	Heavy	Very Heavy
PEAK ACC (mg)	<0.1	0.3	2.4	6.7	13	24	44	83	>158
PEAK VEL (cm/s)	<0.07	0.4	1.9	5.8	11	22	42	80	>160
INSTRUMENTAL INTENSITY	I	II-III	IV	V	VI	VII	VIII	IX	X

Source: <https://strongmotioncenter.org/shake/38443183/intensity.html>.

Second Earthquake M7.1 ShakeMap

- M7.1 Earthquake
- 8:19P Local Time
- July 5th Holiday Weekend
- Epicenter 11.3 miles W of Searles Valley
- 5 miles Deep




Map Version 18 Processed 2019-07-05 10:00:07 AM PDT

PERCEIVED SHAKING	Not felt	Weak	Light	Moderate	Strong	Very strong	Severe	Violent	Extreme
PGA (g)	None	0.2	0.4	0.7	1.3	2.4	4.4	6.0	>10.0
Peak Acc. (mg)	<0.1	0.4	1.6	2.8	5.2	11	20	30	>100
Intensity (MMI)	I	II-III	IV	V	VI	VII	VIII	IX	X

Source: <https://strongmotioncenter.org/shake/38457511/intensity.html>.

Surface Rupture Map





Source: <https://www.usgs.gov/media/images/surface-ruptures-july-4-and-5-ridgecrest-ca-earthquakes>

Design Response Spectrum Comparison

Recorded vs. Expected

- July 4th, 2019 MW 6.4 Summary Graphs of Recorded Spectral Acceleration—Station 5419 PGA: 0.382g





Source: Data: strongmotioncenter.org/cgi-bin/CESMD/iqr_dist_DM2.pl?ID=ci38443183.

Design Response Spectrum Comparison

Recorded vs. Expected

- July 5th, 2019 MW 7.1 Summary Graphs of Recorded Spectral Acceleration—Station CLC PGA: 0.484g



Source: Data: CESMD Internet Data Report, 22 July 2019, strongmotioncenter.org/cgi-bin/CESMD/iqr_dist_DM2.pl?ID=ci38457511.

Reid Middleton Mobilization

- Monitored Earthquakes via USGS
- Monitoring System at NMCSD Recorded Events
- On-Site Thursday, July 11, 2019, 1 Week after the Second Earthquake
- Response Phase:
 - Initial Deployment Teams ~ 24 to 28 People
 - ATC-20 Rapid and Detailed Assessments in Support of NAVFAC SW and NAWSCCL Personnel
 - Initial Focus on Large and Critical Facilities
 - Emergency Shoring and Stabilization
- Recovery Phase:
 - Detailed Damage Assessments and Evaluations
 - DD1391 Development
 - Repair Procurement Development
 - Construction Phase Assistance



INSPECTED
LAWFUL OCCUPANCY PERMITTED

This structure has been inspected and found to be safe for occupancy. (Indicate whether or not the structure is safe for occupancy.)

Inspected Exterior Only
 Inspected Exterior and Interior

Inspected on: _____
Inspector: _____
Inspector ID / Agency: _____

Facility Name and Address: _____

Do Not Remove, Alter, or Cover This Placard until Authorized by Governing Authority.



RESTRICTED USE

Caution: This structure has been inspected and found to be damaged or restricted for use.

Entry, occupancy, and useful use are restricted as indicated below.

Inspected on: _____
Inspector: _____
Inspector ID / Agency: _____

Facility Name and Address: _____

Do Not Remove, Alter, or Cover This Placard until Authorized by Governing Authority.



UNSAFE
DO NOT ENTER OR OCCUPY
(THIS PLACARD IS NOT A DEMOLITION ORDER)

This structure has been inspected and found to be unsafe for occupancy. (Indicate whether or not the structure is safe for occupancy.)

Do not enter, occupy, or use this structure until authorized by governing authority.

Inspected on: _____
Inspector: _____
Inspector ID / Agency: _____

Facility Name and Address: _____

Do Not Remove, Alter, or Cover This Placard until Authorized by Governing Authority.

Reid Middleton Mobilization (cont.)

- Some Staff Experienced in Earthquake Deployments
- Most Staff Trained in ATC-20/45
- Utilized Web-Based Real-Time Scheduling
- Staff from Multiple Offices and Partner Firms
- Multidisciplinary Team
- 5 Days on Site (3 Day Minimum)
- Double Shifts for Many
- Document Everything for Accurate Follow Up
- Information Flow:
 - Daily Reports
 - Briefings
 - Record Keeping



NAWS China Lake Earthquake Impacts

- Earthquake Damage of Varying Degrees to Building Structural and Nonstructural Systems
- Test Facilities Damaged to Varying Degrees
- Road and Utility Infrastructure Damages
- Some Flood Damage from Broken Water Lines
- Emergency Shoring and Contents Retrieval
- Base Access Only for Essential Personnel Initial Days
- Badging and Lodging Demands Increased Due to Additional Workforce


Measuring Earthquake Damage

Leveling Survey of Concrete Slab




Monitoring Aftershock Movement

Concrete and Masonry Crack Gauges




Measuring Aftershock Movement

Seismic and Vibration Monitoring Equipment



Measuring Aftershock Movement

Seismic and Vibration Monitoring Equipment



Earthquake Damage

Surface Faulting



Earthquake Damage

Roadways



Earthquake Damage

Concrete and Masonry Building



Earthquake Damage

Concrete and Masonry Building




Earthquake Damage

Steel Braced Frame Hangar



Earthquake Damage

Steel Braced Frame Hangar



Earthquake Damage

Steel Braced Frame Hangar




Earthquake Damage

Steel Braced Frame Hangar



Earthquake Damage

Steel Braced Frame Hangar



Earthquake Damage

Steel Braced Frame Hangar




Earthquake Damage

Steel Braced Frame Hangar



Earthquake Damage

Concrete Frame and Shear Wall Building



Earthquake Damage

Masonry Building



Earthquake Damage

Masonry Building



NAWS China Lake Earthquake Response and Recovery



Presented by:

David B. Swanson, P.E., S.E.
Principal, LEED AP, F. SEI

SAME San Diego Post Luncheon
September 11, 2019

ReidMiddleton